MOUNTING PROCEDURE

KIT BRACKET RESISTOR HONDA HONDA CB1000 R

HN1-RESIST


KIT

X4. SCREW 3.9X6.5 X1. "ROUND HEAD" SCREW 6X10 X1. SPECIFIC BRACKET X4. CABLE MALE/FEMALE RED (CM 8) X4. CABLE MALE/FEMALE BLACK (CM 8) X2. RESISTOR

WWW.BARRACUDAMOTO.COM


STEP 1

- FIX THE TWO RESISTOR TO THE BRACKET WITH THE N°4 SCREW FROM THE BOTTOM.
- PUT THE SPECIFIC BRACKET UNDER THE FORK PLATE FIXING IT WITH THE SCREW 6X10 IN TO THE HIGHLIGHT HOLE.
- PASS THE BLACK CABLES OF RESISTOR UNDER THE BRACKET.




STEP 2

- CONNECT THE CABLES LIKE SHOWN IN THE SCHEME.
- FIX AGAIN THE HEADLIGHT USING THE ORIGINAL SCREWS LOCKING IT WITH A PAIR OF 5.2 Nm.



CONNECTION SCHEME LEFT SIDE



* NOTE: INDICATORS ADAPTOR NOT INCLUDED INTO THE KIT, SALE SEPARATELY.

BLACK RESISOTR